

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No 128164

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080196-7

RECEIVED FROM

DATE REC'D 1-21-57

P. O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	OR	ACCT. OR W. O. NO.	S. O. NO.
	322	000000	22052								

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY		REMARKS
		ACCEPTED	REJECTED	
7	736319-1 BEARING BALL BEARING ALT # 9 56538	7		

RECEIVED BY	INSPECTED BY	DATE	REJECTS RETURNED ON SHIP MEMO NO.
	Oula	1/21/57	

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No 128165

2961 E. COLORADO ST., PASADENA 8, CALIF.

RECEIVED FROM

DATE REC'D 1-21-57

P. O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	OR	ACCT. OR W. O. NO.	S. O. NO.
	322	000000	22052								

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY		REMARKS
		ACCEPTED	REJECTED	
5	736319-2 BEARING BALL BEARING ALT # 9 56538	5		

RECEIVED BY	INSPECTED BY	DATE	REJECTS RETURNED ON SHIP MEMO NO.
	Oula	1/21/57	

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080196-7